

**25/2182/FUL – 99 Byewaters Site Photos**



*Figure 1: Existing Rear Elevation*



Figure 2: Existing Rear Elevation



*Figure 3: View of flank wall at ground level*



Figure 4: Existing Front Elevation



*Figure 5: View from existing en-suite at the second floor level*



*Figure 6: View from existing ensuite at the second floor level*



*Figure 7: View down from existing second floor side window*



*Figure 8: view from existing flank bathroom window at second floor level*



*Figure 9: view from existing flank bathroom window at second floor level with window open*



*Figure 10: View of flank elevation from streetscene*



*Figure 11: further view of existing flank elevation from streetscene*



*Figure 12: Flank elevation of No. 89 flank elevation with existing flank windows at second floor level*