

Solesbridge House Site Photos:



*Existing retaining brick wall – indication of existing land levels.*



*Existing retaining brick wall – indication of existing land levels. Original Brick and Flint wall to be retained.*



*View of site entrance (right) from highway (north of site).*



*Proposed location of extended gravel drive (approximate).*



*Google image – View of site from carriageway (south)*